

Station Survey – June 2016

STATION	OSBORNE	
CRITERIA	SCORE (1 to 10)	COMMENTS
<b>Appearance and Maintenance</b> <ul style="list-style-type: none"> <li>• Paintwork condition</li> <li>• Graffiti</li> <li>• Rubbish disposal</li> <li>• Cleanliness</li> <li>• Smells</li> <li>• Signage</li> </ul>	3	<p>Multiple instances of graffiti including on timetable signs, on paving and on the shelter.</p> <p>Some paper coffee cups and other litter around one of the bins.</p> <p>No smells</p>
<b>Security, Safety and Lighting</b> <ul style="list-style-type: none"> <li>• Emergency call phone or button</li> <li>• Security cameras</li> <li>• Hidden areas</li> <li>• Oversight by neighbours</li> <li>• Underpass</li> <li>• Pedestrian gates</li> <li>• Lighting – Approaches</li> <li>• Lighting – Platform</li> </ul>	5	<p>No emergency phone evident</p> <p>No cameras evident</p> <p>Substantive amount of foot traffic between nearby community centre and park, across the tracks, to and from the adjacent shopping centre. Mostly youngsters but some adults (survey done on a Saturday afternoon).</p> <p>Some minimal oversight from nearby houses.</p> <p>Pedestrian crossing adequate.</p> <p>Adequate, but some concern about path from nearby community park to south-eastern approach.</p> <p>Adequate</p>
<b>Car and Bike Parking</b> <ul style="list-style-type: none"> <li>• No of Spaces per Mode</li> <li>• Asphalt or gravel?</li> <li>• Bike chain-up secure?</li> </ul>	5	<p>Numerous car parking spaces immediately adjacent and also at the nearby shopping centre.</p> <p>Has bike rack.</p>
<b>Disability Access</b> <ul style="list-style-type: none"> <li>• At Approaches</li> <li>• Ramps to platform</li> <li>• On platform</li> </ul>	4	<p>The northern ramp to platform is asphalt but the southern ramp is made of old timber sleepers, which are in part roughly worn. The latter has some imperfections in the surface but there is a handrail to hold onto.</p> <p>Wheelchair access to southern asphalt ramp is blocked.</p> <p>No ramp to train on platform.</p>
<b>Facilities</b> <ul style="list-style-type: none"> <li>• Toilets</li> <li>• Seats</li> <li>• Food</li> <li>• Shade and Rain Shelter</li> </ul>	6	<p>No toilets on site but there are some at the shopping centre - albeit in a dark lane. Toilets may not be available after hours.</p> <p>Seating adequate</p> <p>Food and some amenity at shopping centre.</p>
<b>Averaged Score</b>	<b>4.5</b>	
<b>Other Comments</b> Opportunity to create Transit Oriented Development. However, shopping centre tenancies face away from the station, with the only aspect presenting to the station is the loading bay.		

Station Survey – June 2016

Photo 1.



Photo 2.



Photo 3.



Photo 4.



**Photo 5.**



**Photo 6.**



**Photo 7.**



Station Survey – June 2016

**Photo 8.**



**Photo 9.**



**Photo 10.**

