

Station Surveys – June 2016

STATION	ADELAIDE SHOWGROUND (Formerly KESWICK)	
CRITERIA	SCORE (1 to 10)	COMMENTS
Appearance and Maintenance <ul style="list-style-type: none"> • Paintwork condition • Graffiti • Rubbish disposal • Cleanliness • Smells • Signage • Other 	9	Excellent condition in regard to all items, reflecting the recent construction and good upkeep since.
Security, Safety and Lighting <ul style="list-style-type: none"> • Emergency call phone or button • Security cameras • Hidden areas • Oversight by neighbours • Underpass • Pedestrian gates • Lighting – Approaches • Lighting – Platform 	9	Call phone on elevator, but no other emergency device apparent. However, station is monitored by 24 hour security cameras. No oversight onto platforms from adjacent areas, but has security cams on platform. Some oversight of the approaches from Rose St housing and/or offices. No oversight of the western approach. Overpass in excellent condition, of a good size and usable by ramps, stairs and elevator. Good lighting, LED lamps Good lighting, LED lamps
Car and Bike Parking <ul style="list-style-type: none"> • No of Spaces per Mode • Asphalt or gravel? • Bike chain-up secure? 	8	Station is adjacent to Showgrounds carpark and to Rose St street spaces. Bicycle lock-up on eastern approach. May suit usage most of the year but would not suffice at show times. Best practice would suggest secure bike lockers.
Disability Access <ul style="list-style-type: none"> • At Approaches • Ramps to platform • On platform 	9	Comprehensive series of ramps for access to platforms, or to elevator level on overpass. Although ramps are lengthy they have an easy gradient with a series of risers alternating with level sections – should be relatively low energy to traverse. Smooth concrete surfaces on ramps, overpass and platforms.
Facilities <ul style="list-style-type: none"> • Toilets • Seats • Food • Shade and Rain Shelter 	7	No toilets Given the station size, there are relatively few seats. Excellent shelter from sun and rain, but not real windbreaks. No amenities for food or drink.
Total Score / Overall Rating	8.5	
Other Comments		

Station Surveys – June 2016

Photo 1.



Photo 2.



Photo 3.



Photo 4.



Photo 5.



Photo 6.



Station Surveys – June 2016

Photo 7.



Photo 8.



Photo 9.



Photo 10.

